



ALL AMERICAN MONITORING

ASC-GSM ALARM PANEL COMPATIBILITY

PANEL TYPE	ASC GSM COMPATIBLE	INTERACTIVE
2GIG GC2	YES	NO
SIMON XT, XTI	YES	NO
NX4, NX6, NX8	YES	YES
CONCORD 4	YES	YES
LYNX 3000, 5200, 7000	YES	NO
VISTA 10SE, 15SE, 20SE	YES	NO
VISTA 10P, 15P, 20P, 21IP	YES	YES
DSC 1555, 632	YES	YES
DSC 5010, 832	YES	YES
DSC 4020, 5020	YES	YES
DSC 1616, 1832, 1864	YES	YES
DSC HS2016, 2032, 2064, 2128	YES	YES
DSC ALEXOR	YES	YES
DSC 9047	YES	YES
DSC IMPASSA	YES	YES
VISTA 10P, 15P, 20P, 21IP	YES	YES

WARNING: THE ASC-GSM IS A STAND ALONE COMMUNICATION DEVICE!

If the RING and TIP (green and yellow wires) of the GSM are hooked in parallel with the phone line (If the landline is still hooked to the RING/TIP or RI/TI of the panel while the GSM is also hooked to the RING/TIP of the panel) the phone line gives very very high voltage back to the device causing a short circuit.

BE SURE PHONE LINE IS DISCONNECTED PRIOR TO GSM INSTALLATION